

DPM2000 : Changing Material Exposure : TN #8

Correct procedure for changing material product codes before making any material exposure tests.

When selecting a new material product code, using Utilities/New Material menus, always click "OK" before making a material exposure test. Be sure the newly selected material product code is displayed in the lower right corner of the main menu bar.

Whenever a material test exposure is performed, the base exposure is determined by the material product code displayed in the lower right corner of the main menu bar. If the material product code displayed is different from the newly selected material product code, then the material exposure test results will be incorrect.



CHECK THAT BOTH PRODUCT CODES MATCH